

**RCD Inspection and Test Report**

**Date:** 16/06/2023

**Technician:** Robert Kuzmanich

**Distribution Board ID:** Basement 1 DB

**Client/Site location:** 38 Mason Street, Cannington WA 6107

**Location on-site:** Basement

**Sub-location:** North wall, adjacent stairwell entry

**Number of RCDs tested:** 31

**RCDs not tested** (these may include RCDs that are tagged out of service, powering critical equipment or those requested not tested by the client): Nil

**Failed RCDs** (if listed, these RCDs have failed inspection and testing and require repair or replacement by qualified electrician before being put back into service. See fail report for details): NA

**Technician comments:** Nil

**Photo 1:**



**Photo 2:**



All RCDs located in the electrical switchboard detailed above (excluding those listed in "RCDs not tested" section) have been inspected and tested to Australian Standard AS/NZS 3760 - In-service safety inspection and testing of electrical equipment and RCDs.