

Exit and Emergency Luminary Report

Exit / Emergency Luminary						
Asset Type	Fitting Type	Location	Sub Location	Pass or Fail	Date	Comments
Emergency Light	Spitfire Luminary - Recessed	Office	Above reception	Pass	11th July 2023	
Emergency Light	Spitfire Luminary - Recessed	Office	Hallway	Pass	11th July 2023	
Emergency Light	Flood Light - Twin	Store Room	North Wall	Pass	11th July 2023	
Emergency Light	Spitfire Luminary - Recessed	Office	Kitchen Area	Pass	11th July 2023	
Emergency Light	Emergency Batten - 600mm	Car Park	External Wall	Pass	11th July 2023	
Exit Light	Exit Sign - Wall Mounted	Rear Exit	Above rear door	Pass	11th July 2023	
Exit Light	Exit Sign - Ceiling Mounted	Front entrance	Above door	Pass	11th July 2023	

Inspection and testing carried out in accordance with AS/NZS 2293.2.2019