

Fire Equipment Report

| Fire Equipment | | | | | | | | |
|-------------------------|-------|----------|------------------|---|---------------|--------------|----------------|----------|
| Type | Size | Location | Sub-location | Level 4 Service or Replacement Due YYYY/MM/DD | Service Level | Pass or Fail | Date | Comments |
| ABE Dry Chemical Powder | 4.5kg | Hallway | Nearby rear exit | 2028-07-11 | 2 | Pass | 11th July 2023 | |
| CO2 | 3.5kg | Office | Behind reception | 2028-07-11 | 2 | Pass | 11th July 2023 | |
| ABE Dry Chemical Powder | 1.5kg | Vehicle | 1HDD 8932 | 2028-07-11 | 2 | Pass | 11th July 2023 | |

Inspection and testing carried out in accordance with AS 1851-2012